


Art. No. 6085 **Grounding Clamp for ECOFLEX® 10**

1. Carefully cut and remove the cable sheath at a length of 25 mm, make sure that the Braid and the Copper-Foil is not damaged!



2. Open the grounding clamp, and spread the aluminium shell and then push the cable into the shell. Re-bend the shell until it fits tightly around the cable.



3. Close the grounding clamp outer shell and fasten the screw.



Important!

Connect the grounding cable of the clamp to a good ground terminal!